

Smooth Bore & Deluge Tips

For maximum reach, smooth bore tips create concentrated waterflow for use with either handlines or monitors while using lower pressures of 50 or 80 psi. Elkhart offers a wide variety of discharge sizes to suit any need. Additionally, Elkhart's stacked tips allow you to customize the smooth bore to meet your needs in the field.



HANDLINE NOZZLES

SMOOTH BORE & DELUGE TIPS







Figure 1	SLUG	
		<p>186-A</p> <ul style="list-style-type: none"> • Leader threading <p><i>Fig. 1</i></p>
Figure 2	SINGLE SMOOTH BORE TIPS – HANDLINE	
		<p>185-A</p> <ul style="list-style-type: none"> • Leader threading • Bumper <p><i>Fig. 2</i></p>
Figure 3	SINGLE SMOOTH BORE TIPS – HANDLINE	
		<p>185-B</p> <ul style="list-style-type: none"> • Bumper <p><i>Fig. 3</i></p>
Figure 4	SINGLE SMOOTH BORE TIPS – HANDLINE	
		<p>187-A</p> <ul style="list-style-type: none"> • More compact than other tips <p><i>Fig. 4</i></p>
Figure 5	SINGLE SMOOTH BORE TIPS – HANDLINE	
		<p>188-A</p> <ul style="list-style-type: none"> • Longer tip for improved stream quality • Bumper <p><i>Fig. 5</i></p>
Figure 6	SINGLE SMOOTH BORE TIPS – HANDLINE/DELUGE	
		<p>187-CAF</p> <ul style="list-style-type: none"> • For applying CAF <p><i>Fig. 6</i></p>

Figure 7	SINGLE SMOOTH BORE TIPS – DELUGE	
		<p>181</p> <ul style="list-style-type: none"> • Classic deluge tip <p><i>Fig. 7</i></p>
Figure 8	SINGLE SMOOTH BORE TIPS – DELUGE	
		<p>181-3A</p> <ul style="list-style-type: none"> • Built-in stream shaper <p><i>Fig. 8</i></p>
Figure 9	SINGLE SMOOTH BORE TIPS – DELUGE	
		<p>181-5A</p> <p><i>Fig. 9</i></p>
Figure 10	STACKED SMOOTH BORE TIPS – HANDLINE	
		<p>ST-185-A</p> <p><i>Fig. 10</i></p>
Figure 11	STACKED SMOOTH BORE TIPS – MASTER STREAM	
		<p>ST-194</p> <ul style="list-style-type: none"> • Leader threading <p><i>Fig. 11</i></p>
Figure 12	STACKED SMOOTH BORE TIPS – MASTER STREAM	
		<p>ST-195</p> <ul style="list-style-type: none"> • Leader threading <p><i>Fig. 12</i></p>
Figure 13	STACKED SMOOTH BORE TIPS – MASTER STREAM	
		<p>ST-197-A</p> <ul style="list-style-type: none"> • Leader threading <p><i>Fig. 13</i></p>

HANDLINE NOZZLES

1-32